

The Expanding World of Nanofabrication – *an update from NanoFabrication Kingston*

January 23, 2023

Good day,

You are receiving this important update as a user of NFK, as a supervisor of a user, or as someone who requested to receive these updates.

Maskless photolithography

The lamp was changed on the SF-100 Maskless Lithography System at NFK, so exposure time for all processes will be shorter now. If you need to use this tool, check with me about the new exposure time. You may need to do an exposure matrix to find out.

Sputter system down

There is currently a communication error with the turbo pump controller. The sputter system will be down while I work with the supplier to resolve the issue.

See you at the lab!

Graham Gibson

Lab Operations Manager, NanoFabrication Kingston
Queen's University
945 Princess St.
Kingston, ON
K7L 0E9
gibsong@queensu.ca

If you want to opt out of receiving messages containing optional content, please contact gibsong@queensu.ca. You will continue to receive messages with required content until you complete the NFK Check-Out procedure. Contact gibsong@queensu.ca for more details.